

McLaren 601A


Schematics

McLaren Audio


A Division of Amplifier Consultants Ltd, P.O. Box 13359, Johnsonville, Wellington, New Zealand.

Phone (64) (4) 4786669

Fax (64) (4) 4786669



McLAREN 601A SCHEMATIC



McLAREN 601A UPDATE SCHEMATIC Revised
 1/8/94 to update to 1994 performance
 UPDATE 3/97 INVOIC'S REPLACE BY 24V FAST RECTIFIERS
 R110 9AP11 REPAIRS BY BR245 B FETS